

1151879 - R8.SDMS

Asarco

RECEIVED
MAR - 2 2010
ECEJ

To: Iver Johnson
From: Jon Nickel
Date: February 25, 2010

Subject: 2009 Cleaning and Demolition Project - Demolished, Cleaned, and
Remaining Structures - Former Asarco East Helena Facility

Enclosed please find two copies of the above referenced exhibit. The enclosure reflects the current status of the East Helena Facility, as further described in the latest version of Appendix A. Please note that the Exhibit shows that the soda ash and lime silos have been cleaned. As you may recall, the bin ventilation baghouses to both of these structures have been cleaned but product remains within each of the silos.

Please let me know if I can provide further information.

Enclosure

cc: Linda Jacobson
Cindy Brooks
Marc Weinreich

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1151879

SITE NAME: EAST HELENA RCRA CORRECTIVE ACTION

DOCUMENT DATE: 02/25/2010

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☒ OVERSIZED
- ☐ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

EXHIBIT 3-2 2009 Cleaning and Demolition, Demolished, Cleaned, and
Remaining Structures

